



SPOT X Firmware Update

Release Update – September 9, 2019

New Features

- Support for new Bluetooth-enabled version of SPOT X
- Pin/passcode screen lock

Improvements

- Support for half-hour time zones

Bug Fixes

- Backlight error while typing a message

NOTE: Bluetooth capability is not available for non-Bluetooth SPOT X devices.