



SPOT Trace Firmware Update

Release Update – July 12, 2021

Firmware Version 1.10

Improvements

- Addresses elevated battery draw when unit was OFF.